
OUR REFERENCE NO.: IMPJ-0027A (033327-054)

MAY 1 5 2007








FIG. 2 (Prior Art)





FIG. 3

REPLACEMENT SHEET



OUR REFERENCE NO.: IMPJ-0027A (033327-054)

REPLACEMENT SHEET




FIG. 5A




FIG. 5B




FIG. 5C

OUR REFERENCE NO.: IMPJ-0027A (033327-054)

4/27




FIG. 5D




FIG. 5E

REPLACEMENT SHEET




FIG. 5F






FIG. 6


REPLACEMENT SHEET




REPLACEMENT SHEET




REPLACEMENT SHEET



REPLACEMENT SHEET



REPLACEMENT SHEET



OUR REFERENCE NO.: IMPJ-0027A (033327-054)

REPLACEMENT SHEET




FIG. 12A




FIG. 12B

REPLACEMENT SHEET




FIG. 12C







FIG. 13







15/27



REPLACEMENT SHEET



REPLACEMENT SHEET



REPLACEMENT SHEET

18/27

154-




FIG. 19

OUR REFERENCE No.: IMPJ-0027A (033327-054)

REPLACEMENT SHEET

19/27

MOSCAP Tunneling Junction




FIG. 20






FIG. 21

REPLACEMENT SHEET





FIG. 22

REPLACEMENT SHEET



REPLACEMENT SHEET




FIG. 24

REPLACEMENT SHEET




FIG. 25

OUR REFERENCE NO.: IMPJ-0027A (033327-054)

REPLACEMENT SHEET




FIG. 26

REPLACEMENT SHEET




FIG. 27

REPLACEMENT SHEET




FIG. 28

OUR REFERENCE NO.: IMPJ-0027A (033327-054)

REPLACEMENT SHEET




FIG. 29A




FIG. 29B